

Important Information

Please note the following to prevent damage and malfunction of the measuring instrument:

- Please observe its storage and working temperature and protection level.
- Do not open or modify the instrument.
- Keep the socket for the charger covered when these are not in use.
- The measuring instrument has to be used in a mounting device or other suitable fixture. We recommend a device with a split mounting bore of dia. 8 H7 mm.
- For cleaning of the front cover/dial glass use a soft cloth moistened with a neutral reading cleaning agent. Never use organic solvents like thinners and petrol.
- For cleaning of the measuring spindle use a cloth moistened with alcohol. Do not apply oil on to the measuring spindle.



1 Introduction	1
2 Specification	1
3 Preparation	2
3.1 Power supply	2
3.2 Swivelling of display unit	2
3.3 Mounting	3
3.4 Exchange contact point	3
4 Operation	3
4.1 Setup	3
4.2 Operation in Measuring Interface	4
1) Key Functions	4
2) Zeroing Readings	4
3) Data Browse	5
4) Tolerance	7
5 Save/Print/Upload	8
5.1 Save Data	8
5.2 Data Transmission	8
5.3 Printing	8

Long Term Storage

Up to a year from -10°C to $+35^{\circ}\text{C}$. The storage temperature between $+10^{\circ}\text{C}$ and $+25^{\circ}\text{C}$ is recommended.

- To prevent the battery self-discharging or the reduction in the functionality or damage, the rechargeable battery should be charged a minimum of once per 3 months.
- After a long storage period (over 6 months) may lead to a limitation of the battery capacity after the first discharge. Through repeated charge - discharge cycles, the rechargeable battery may restore its capacity.

1 Introduction

The Inductive Digital Comparator EDC2000 is a versatile precision measuring instrument for the economical application in the production process and in the inspection room.

Please read the operating manual carefully to ensure best use. We reserve the right to make modifications on the measuring instrument as well as on this instructions.

2 Specification


Measuring Span : 2/0.0787" (mm/inch)
 Resolution : 0.0001/0.000005" (mm/inch)
 Total Stroke : 4 mm
 Measuring force : 0.7~0.9 N
 Measuring system : LVDT
 Display : LCD
 Memory : 999 readings
 Battery : Li-Ion

Operating time : approx. 12 h
 Charging time : approx. 3h
 Class of protection : IP 54
 Operating temperature : +5° C to +40° C
 Storage temperature : -10° C to +60° C
 Data Interface : USB, RF wireless
 Weight : 165 g

Standard Accessories

- Charger/adaptor
- Data/charge cable
- Operation manual
- Inspection certificate

- 1 Display
- 2 Operating Keys
- 3 Mounting Shank
- 4 Measuring Spindle (in Rubber Bellows)
- 5 Contact Point
- 6 Preliminary Screw
- 7 Display Unit
- 8 Contactless Key Window
- 9 Cover Screw
- 10 USB Socket



- | | |
|-------------------|---------------------|
| 12 Readings | 6 Setting Group No. |
| 13 Unit | 7 Contactless Key |
| 14 Signal | Wireless |
| 14 Directions | USB |
| 23 Analog Display | Print |
| 24 Scale | |
| 25 Span | |
| 3 ABS Absolute | MIN Minimum |
| TOL Tolerance | PRE Preset |
| MAX Maximum | |
| 4 Indicator | |
| 5 Readings Lock | |



Duration of key activation



Short Press(<1 sec.)



Long Press(>2 sec. or Wait for Indicator light to turn white.)

Key Functions

	Measuring	Setup	Browse	Tolerance
Power/ ZERO	Turn on or off			
	Zeroing display	Select setting group	Delete record / Confirm delete	
Up/ SET	Enter Setup	Exit	Exit	Exit
	Lock /Unlock display	Upward / Increase	Page up	Upward / Increase
Down/ TOL	Enter tolerance setting	Enter/Exit search input		Enter/Exit search input
	Turn on/off tolerance monitor	Downward / Decrease	Page down	Downward / Decrease
Right/ DAT	Enter data browse			
	Save / Upload / Print	Move next		Move next
Contactless Key	Zeroing	Can be turn ON/OFF in setting.		
	Save / Upload / Print			

3 Preparation

3.1 Power supply

The instrument can be powered either by the integrated Li-ion rechargeable battery or the charger via the USB interface.

The battery power is displayed in the boot display.


Note: As the first use, the battery should be charged for 5 hours at least.

Fully charged

Medium charged

Battery low

3.2 Setting of the swivelling operating and display unit



3.3 Mounting

The comparator is used usually mounting on a stand or other device.
The stand or the device should be with a split mounting bore of $\Phi 8 \text{ H7 mm}$.
To ensure smooth movement of the measuring spindle, do not use a screw to clamp the mounting shank directly.

3.4 Exchange contact point

- Unscrew a light contact point;
- Take off Rubber bellows, hold the spindle tight with a plier using a piece of cloth to protect the measuring spindle from damage
- Use the another plier to unscrew the contact point.

Important! Ignoring this advice may lead to damage of the interior of the instrument or of the measuring spindle.



3.5 Setting of preliminary stroke

The preliminary stroke is set with the hexagon wrench in the range of $-1,3 \text{ mm}$ to 0 .

Note: When a workpiece is to be inserted into a measuring device without lifting up the measuring spindle, adjusting the preliminary stroke will be useful.



4 Operation

In order to obtain highest accuracy, the instrument requires a warm-up period of about 5 minutes.

4.1 Setup



Enter Setup

The settable parameters are grouped into 3 groups.

Group 1

fa. The scale or range of analog-display

fb. Unit

mm: millimeter
in: inch

fc. Directions

▲ Measuring spindle retracted direction is the one in which value increases.

▼ Measuring spindle extended direction is the one in which value increases.

Scale µm/mm	Span µm/mm
0.1 / -	±2 / -
0.25 / -	±5 / -
0.5 / -	±10 / -
1 / 0.05	±20 / ±1
2.5 / 0.1	±50 / ±2
5 / 0.2	±100 / ±4
10 / 0.4	±200 / ±8
25 / 1	±500 / ±20





Group 2

2a. TIR set

Max:

To display the maximum of measuring value.

Min:

To display the minimum of measuring value.

Max Min: To display value(MAX-MIN).

* When the MAX and MIN are all turn on, to display the value of MAX-MIN.

2b. PRE:

To display the value in which added the preset value.



Group 3

3a. Contactless Key: Contactless key is turn on, when it is displayed.

3b. Wireless: Wireless data transfer is turned on, when displayed.

3c. USB: USB data transfer is turned on, when displayed.

3d. Print: Printing data transfer is turned on, when displayed.

* If one or two or all of is/are turn on, press the key in measuring interface, the readings will be saved and be sent through the specified communication path.

** If the contactless key is turn on, its function is same as the key .

4.2 Operation in Measuring Interface

1) Key Functions



Turn ON/OFF

ZERO

Zeroing the readings.



Browse data in memory.

DAT

Save / Send / Print current reading.



Enter tolerance setting.

TOL

Turn on/off tolerance alarm.



Enter Setting.

SET

Lock/unlock the reading.



Zeroing the readings, equivalent to



ZERO

Save and send(or print) current reading, equivalent to




DAT

2) Zeroing Readings

In ABS, zeroing readings will turn to relative measurement mode.

In PRE, the reading will zero to the preset value.

In the others, the readings will be zeroed. The analog display will also be zeroed.




*** Search Input:**

The comparator can save up to 10 of preset values that had been inputted. After reaching 10, the new value is stored and the oldest value is discarded.

The order will be rearranged according to the frequency of use.

3) Data Browse

  Enter/Exit data browse. To browse the data save in memory.




TIR Measuring

There 3 types of TIR, MAX, MIN and MAX-MIN.



4) Tolerance



* Search Input:

The comparator can save up to 10 of upper and lower limit values that had been inputted.

After reaching 10, the new value is stored and the oldest value is discarded. The order will be rearranged according to the frequency of use.

5 Save/Print/Upload

On measuring display:

  will printing or/and uploading the current readings, at the same time save it.



Contactless

If the contactless key is turned on, it equivalent to short press key 

5.1 Save Data

When the above operation is performed, the current reading will be stored in memory first. The stored data can be reviewed and deleted, or uploaded via the data acquisition software.

5.2 Data Transmission

Data can be transferred via one or both of the specified paths: USB , wireless .



Set  turning on

Connect Digital Comparator to PC with the USB Cable
Run data acquisition software on PC side.



Set  turning on.

Insert the Wireless transceiver to USB port on PC.

Run data acquisition software on PC side and register the instrument.

Multiple comparators can transfer data with the same transceiver.



5.3 Printing



Set  turning on.

Turn on the wireless printer.

  To print the measuring report.

When **"*****"**(exceeds the measurement stroke) is displayed,   twice will finish the report and ready for a new report.



To finish a report

Report			

S/n : 6211801008			
Mode: REL mm			
001	25	8220	
002	25	8217	
003	25	8221	
004	25	8199	
005	25	8222	
006	25	8222	

X: 25.8217			
S: 0.0009			

2018-05-03 8:53			